

Fig. 1

A side view of the mechanical assembly. It shows a large, rounded upper housing (17) with a horizontal flange (13) at the top. The housing is supported by a base (11) via a central vertical support (12) and two side supports (31a, 31b). A horizontal rod (18) passes through the side supports. A curved line (15) indicates a pivot or hinge mechanism. The entire assembly is mounted on a base (11). The word "SIDE" is written below the diagram.

111 29

10032634-10601




Fig. 3




Fig. 4




Fig. 5

1003234-10501




Fig. 5A




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 12




Fig. 11




Fig. 13

ELECTRICAL BLOCK DIAGRAM




Fig. 14